

SECRET
(When Filled In)

EXCLUDED FROM AUTOMATIC
DOWNGRADING AND
DECLASSIFICATION

2		5	
3		6	
4		7	
		8	

ADVANCE COPY ☐ ISSUED ☐ SLOTTED

REPRODUCTION OF THIS COPY PROHIBITED

BY: _____ AT: _____ Z

DISSEM BY 46 PER _____ # _____

ACTION UNIT

COMMO 7

INFO

FILE, VR

LOGS 4

25X1A

ACTION NO.

096

SECRET 010252Z DEC 70 CITE [REDACTED] 0765

25X1A

25X1A

1 DEC IN 216637

REF: DIRECTOR 087352 SD

25X1A

1. RECENT [REDACTED] AIR CONDITIONING FAILURE WAS CAUSED BY LOSS OF ONE PHASE [REDACTED] POWER. [REDACTED] POWER ENTERS COMPOUND THROUGH DELTA TO WYE TRANSFORMER BANK SO THAT SOME VOLTAGE EXISTED ON EACH LEG. ALL BURNED OUT MOTORS HAVE MOTOR PROTECT DEVICES, BUT HEATER COILS ARE INSTALLED IN ONLY TWO OF THREE PHASES. [REDACTED] STILL TRYING TO DETERMINE IF THIS IN ACCORDANCE WITH APPROVED DESIGN.) CANNOT ASCERTAIN CURRENT AND VOLTAGE CONDITIONS AT MOTOR CONTROL BOXES WHEN BASE POWER LOST PHASE, BUT THE SAME LEG IS UNPROTECTED ON ALL MOTORS THAT BURNED UP. MOTOR RESETS WERE TRIPPED ON CONTROL BOXES OF ALL BURNED MOTORS, BUT CANNOT DETERMINE IF MOTORS BURNED IN SPITE OF THIS OR IF RESETS TRIPPED BECAUSE MOTORS BURNED.

25X1A

25X1A

25X1A

REC'D

2. WE HAVE BEEN OPERATING STATION SWITCHGEAR UNDER SOMEWHAT MODIFIED PROCEDURE BECAUSE OF AIR CONDITIONING RECYCLING PROBLEM. AS INSTALLED, ALL A/C COMPRESSORS START UPON POWER RESTORATION

C
3 DC
1 EX
SA
P1211

3 PE
4 C
5 PE

25X1A

SECRET

Approved For Release 2000/06/14 : CIA-RDP78-06505A000500040003-5

SECRET
(When Filled In)

EXCLUDED FROM AUTOMATIC
DOWNGRADING AND
DECLASSIFICATION

ADVANCE COPY ☐ ISSUED ☐ SLOTTED

REPRODUCTION OF THIS COPY PROHIBITED

1	5
2	6
3	7
4	8

BY: _____ AT: _____ Z

DISSEM BY _____ PER _____

ACTION UNIT

INFO

FILE, VR

ACTION NO.

1 DEC 70 10 25

25X1A

PAGE 2 0765 S E C R E T

AFTER A POWER FAILURE AND RUN UNTIL THEY PUMP DOWN. ONCE UNLOADED, THEY CYCLE UP AT 20 SECOND INTERVALS. HOWEVER, THIS INITIAL LOAD IS TOO GREAT FOR AUTOSTART GENERATORS AND WILL NOT ALLOW AUTOSTARTS TO START. TIME DELAY RELAYS ARE ON ORDER THAT WILL SEQUENCE THE COMPRESSORS AND ELIMINATE THIS PROBLEM. WHILE AWAITING THEIR ARRIVAL, SWITCHGEAR MASTER SWITCH WAS PLACED IN "MANUAL" POSITION AND EMERGENCY POWER WAS BROUGHT UP BY MANUALLY TRIPPING AND CLOSING PROPER BREAKERS AND MANUALLY CYCLING THE COMPRESSORS. THIS ELIMINATED PROTECTIVE FEATURES OF THE SWITCHGEAR, BUT IT WAS BELIEVED THAT INDIVIDUAL MOTOR CONTROLS WOULD PROVIDE ADEQUATE PROTECTION.

25X1A

3. HAVE RETURNED SWITCHGEAR TO AUTOMATIC MODE TO INCLUDE SAFETY TRIP FEATURES. LEAVING INDIVIDUAL EMERGENCY GENERATOR CONTROLS "OFF." EVERY MOMENTARY POWER DIP WILL HAVE TO SWITCH TO "MANUAL," CLOSE PROPER BREAKER AND SWITCH BACK TO "AUTO." FOR PROLONGED POWER OUTAGES WILL SHUT OFF A/C COMPRESSOR MOTORS, START GENERATORS, AND CYCLE UP COMPRESSORS (BREAKERS CLOSE AUTOMATICALLY AFTER EMERGENCY GENERATORS RUNNING). BELIEVE THIS PROCEDURE WILL PREVENT FUTURE FAILURES AND PERMIT ACCEPTABLE OPERATION. GP-1,

S E C R E T

SECRET